RISO, INC. **PARTS CHANGE INFORMATION**

PART: RC6300 SYSTEM ROM **ISSUE #: 030**

JAPAN:TI-074

NEW PART NUMBER: 886-37107A NEW DESCRIPTION: System Main ROM 33/V1.07A OLD PART NUMBER: 886-37105 OLD DESCRIPTION: System Main ROM 33/V1.05	[ ] New [X] Modified [ ] Obsolete [ ] Other
Compatible: [X] Not Compatible: [ ] Old/Obsolete: [N]	

CHANGE REASON	MANUFACTURING CUT-IN	MODEL(S):
[ ] Cost Effective [X] Eliminate Claims [ ] Easier Operation [ ] Other	SERIAL #: N/A	RC SERIES

The “Replace Master Roll” indication is not displayed when the roll end tape actuates the Roll End Detector.

The RC 6300 has updated ROM SP33 / V.1.05 to ROM SP33 / V.1.07A to correct this problem.